
CITY OF BALTIMORE WET SMOKE AND DYED I	Page 1 of 3			
Sewershed: Low Level Subsewershed: 44	Company: REI/DRAYCO	Date: 08/25/2008		
Test Type: Smoke	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R. Crew: 04		
Manhole ID: S17M023MH	Test ID: 1029-557	Notifications Made:X_ Residents, Fire, 311		

**Field Sketch:** (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)



CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM								Page 2 of 3					
,	Sewershe Subsew			Company: REI/DRAYCO						Date: 08/25/2008			
Test Type: Smoke					Ground Condition:				Supervisor: E.R. Crew: 04				
rest rype. Smoke				Dry: X Damp:_ Wet:_					Notifications MadeX_				
Manhole ID: S17M023MH				Test ID: 1029-557			Residents, Fire, 311						
			ohors						lation locations, street names, building addresses				
rieiu 3	Ketch. (3110	w all			ations, def							JI 15, 5	lieet names, building addresses
Defect		/	Address		Source			Sector		nage			
No.					Type					ea	_		Photo Number
1	S17M(	)23N	1H		01	0	2	02		6	01		1029-557_OB01-01.jpg
											<u> </u>		
	<del>                                     </del>										1		
	<u> </u>										1		
									1				
					OB			ION CO	DES				
04 114	Sour			0.4	5 16	Loca					Sector	0.4	Severity
			MH Frame		Paved C	onc.					Public	_	No Smoke
			Storm Drain		Asphalt	)tha:		Field/W	ooas	02	Private		Trace
	eanout		Catch Basin Storm MH		Paved C Drivewa			Alley Golf Co	urco				Moderate Major
	ownspout ea Drain		Storm MH Storm Ditch		Sidewal		14	Other	urse			υ4	Major
	vy. Drain		Excavation		Curb	IX.	14	Outer		<del>                                     </del>			
			Water Line		Yard - F	ront							
			Tele. Pole		Yard - B								
	dg. Interio				Yard - S								

PAGE 3 of 3

## CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY LOW LEVEL SEWERSHED

BALTIMORE CITY PROJECT 1029 REI/DRAYCO

Unique Test ID: 557	' Date	: 08/25/2008	Basin: LL - 44	Manhole ID: S17M023MH
Defect No: OB01	Supervisor: E.R.	Crew: 04		Dye Test Recommended: N

Location: S17M\_\_023MH

Source Type: 01 Main Sewer Sector: 02 Private

Location: 02 Asphalt Severity: 01 No Smoke Drainage Area: 6

Comments: MANHOLE S17M\_\_023MH HAS A STORM DRAIN LID.

## **SMOKE TEST PHOTOGRAPHS**



Photograph No: OB01-01 Filename: 1029-557\_OB01-01.jpg